











K3D SA





No	L[mm]	W[mm]	H[mm]	PCS	BOX
034	761	396	18	3	2/3
176	832	400	15	1	2/3
177	832	400	15	1	2/3
178	757	400	15	1	1/3
232	1302	430	36	1	1/3
318	433	400	15	1	1/3
345	1270	400	15	1	1/3
346	821	400	15	1	1/3
405	1269	60	15	1	1/3
5101	1297	402	2,5	1	1/3
5102	1297	402	2,5	1	1/3
680	832	50	22	1	2/3
681	832	50	22	1	2/3











7




8





9



10

K1 x2





Ø6,4x50mm


N2 x1



4mm HEX



11








12

G1 x 32




H x 1





A=B ≡ 90°



13






14




15



16



17



18





T4 x2




W2 x4




Y1 x6




I




II




III




IV



V



VI




19

U1x2







Ø33mm

X4x2



M4x25mm



20

U1x1






Ø33mm














X4x1



M4x25mm



21



22

